

Warranty (Defect) inspection report

Inspection Detail

Date / Time of Inspection:

Wednesday, April 20 + @ 09:00 A

Type of Report:

Warranty (Defect) sper on

Address of Property:

Client Details

Client Name:

Client Email Address:

Client Phone:

Real Estate Agent Details

Agent Name:

Company:

Mobile:

Email Address:

Inspector Details

Inspector Name:

Inspector Office:

Inspector Phone:

Inspector Email Address:

ISPECT

Warranty (Det ct) ispection report

iSPECT Building Inspections offers property inspection so vices or your property, by highly qualified inspection experts. Each of the inspectors agrees to comply with and are performance managed against iSPECT's Code of Conduct. For further information about your report call 1300 477 328 or for further information on our code of conduct please visit https://ispect.com.au/code-of-conduct



TABLE OF CONTENTS

2. Definitions 3. Inspection Agreement 4. Terms & Conditions 5. Hallwars and ventural living spaces 6. Kitchen	6 7 9 11
4. Terms & Conditions 5. Hallwars and ventral living spaces 6. Kitchen	9
5. Hallwars and ventral living spaces 6. Kitchen	11
6. Kitchen	
	13
7. Laundry	14
8. Bedrooms	17
8.1. Bedroom 1	17
8.2. Bedroom 2	18
8.3. Bedroom 3	19
8.4. Bedroom 4	20
9. Bathrooms	21
9.1. Bathroom 1	21
10. Ensuite	22
10.1. Ensuite 1	22
11. External of property > Exterior	23
12. External of property > Roof areas	30
13. External of property > Sub floor areas	32
14. Findings and summary	33
15. iSPECT Building Inspections	34

1. Description of property Brief description of the building and other structures on the property: Type: **Bedrooms:** 4 1 **Bathrooms:** 1 **Ensuites:** Double Car Park: Height: Two Story Building: Mixed construction Piers: Concrete Floor: Roof: Tile 2020s Age: Image of property:



Weather at time of inspection? Fine Was the property furnished at time of inspection? To conduct an inspection in accordance with AS 4349.1 the property would be vacant of all furnishing to enable Please note: a thorough visual inspection. Was there evidence of any extensions at time of inspection? No **Comment:** to property Service: **Electricity:** Not tested **Comment:** Gas: **Comment:** Water: Yes - Not tested **Comment:** Sewer: Yes - Not tested Comment: Yes - Not tested **Drainage: Comment: Smoke Detector:** Yes - Not tested Comment:



2. Definitions	
Definition of terms used	to describe the current state of repair for each item inspected
Condition Visually Fine:	When the Inspector has viewed the subject area and sees no major defect, and sees no safety hazard.
Minor and/or Major Defect	Any defect observed to the property in accordance with the Standards and Tolerances where applicable, where repair works must be carried out. Repairs should be carried out by a suitably qualified or licenced trades person.
Incomplete Item	Any item that is deemed incomplete at the time of the inspection, but not deemed a defect at that time.
Unable o Inspect Due to Access	An area of the site where there is insufficient, unsafe or unreasonable access.
Not Applica /A):	When the subject field doesn't make up any part of the inspected property.
Report Defin. ion	
Shower Recesses:	not real leaks or show incorrect waterproofing if silicon liquid or masonry sealant has been opplied prior to the inspection. Such application is temporary waterproofing measure are may be the for some months before breaking down. The tests of shower recesses are intedering ing water within the recesses and visually checking for leaks. As shower are only decked by a short period of time, prolonged use may reveal leaks were not detected at a time of specials. No evidence of a current leak during inspection does not acceptable and at the shower does not leak.
Glass Caution:	Glazing in some by sing (a tilt before 1978) may not necessarily comply with current glass safety standards \$12.8. In the interests of safety, glass panes in doors and windows especially in high raffice was should be replaced with safety glass of have shatterproof film installed.
Stairs & Balustrades:	The Australian Building Code 3.9 require that sovering stairs, landings and balustrades ensure the safety of all occupants as visitors a building. Those built prior to 1996 may not comply with the current standard. The property of the prior to 1996 may not comply with the current standard.
Swimming Pools:	A pool is subject to a special purpose poperty and is not applicable to this report.
Rooms Below Ground Level:	Rooms under the house or below ground level (whenler they be habitable or not) may be subject to dampness and water penetration. They are the ways installed correctly to these areas or could be blocked. It is common to have tamp a blems and water entry into these spaces, especially during periods of heavy rate all and rely not be evident on the day of the visual inspection. These rooms may also reach we could approval. The purchaser should make their own enquiries to Council to ascerta.
Owners Corporation:	If the property is covered by an Owners Corporation (Strata The) APP recommend that an Owners Corporation search be conducted to ascertain their financial portion, we level of maintenance afforded and any other relevant information that may in eact your leafer ownership of the property.



3. Inspection Agreement

Requirement for inspection agreement

AS 4349.1 - 2007 requires that an inspection agreement be entered into between the inspector & the client prior to the conduct of the inspection. This agreement sets out specific limitations on the scope of the inspection and on limits that apply in carrying it out. Where specific State or Territory requirements apply in addition to the scope of work in this agreement, or where the inspector and client agree to additional matters being covered, that additional scope is listed at the end of this agreement. It is assumed that the existing use of the building will continue.

AS 4349.1 - 2007 requires that the basis for comparison is a building of similar age and similar type to the subject building and which is in reasonable condition, having been adequately maintained over the life of the building. This means that building being inspected may not comply with Australian Standards, building regulations or specific state or territory requirements applicable at the time of the inspection.

Purpose of inspection

The purpose of the inspection is to provide advice regarding the condition of the property at the time of the inspection.

Reasc able ccess to the property at time of inspection?

Yes

NO

Areas where reasonable erry is depict to the inspector or where reasonable access is not available are excluded from and do not form part of the inspection. Access unitations may include legal right of entry, locked doors, security system, pets, furniture or other obstructions. Physical access limitations may include height, narrow boundary clearance, thick vegetation, small roof or crawl space and adverse weather conditions. The report shall identify any area or item within the scope of the inspection that was not inspected and the factor that never year in spection.

The extent of accessible areas shall be determined in the inspector at the time of inspection based on the conditions encountered at that time. The inspection hall include option accessible areas and areas that are within the inspector's line of sight and close enough to enable reasonal and said approximately said to the conditions.

Reasonable access includes a prerequisite that the prantum clearances specified in the table below are safely available. Dimensions for reasonable access:

- Roof Interior: 400mm x 500mm access hole; 600mm x 60t are crawl space; and accessible from a 3.6m ladder;
- Roof exterior: 400mm x 500mm access hole; 600mm x 600mm crawl space; and accessible from a 3.6m ladder placed on the ground

Supplementary notes:

- Reasonable access does not include the cutting of access holes of the revolution of access and bolts or any other fastenings or sealants to access covers.
 - Sub-floor areas sprayed with chemicals are not be inspected unless it is fe to do so.



50/x

Conditions

An inspection report may be conditional on:

- Prevailing weather conditions or recent occupancy and use of services that mightaffect observations.
- Information provided by the client or agents of the client.
- · Deliberate concealment of defects.
- · Any other relevant factor limiting the inspection.

Scope of inspection

What is not reported on, general exclusions detailed in AS 4349.1 - 2007

- Parts of a building that are under construction;
- The inspection is not intended to include rigorous assessment of all building elements in a property;
- Defects that would only be apparent under particular weather conditions or when using particular fittings & fixtures;
- Defects not apparent due to occupancy or occupancy behaviour e.g. non-use of a leaking shower;
- The inspeg ort is not a certificate of compliance of the property within the requirements of any Act, regulation, by-law and is not a warranty against problems developing with the building in the future; ordinance, lo
- buil ng work or of work not compliant with building regulations; Unag hori
- rsh, matters, matters concerning easements, covenants, restrictions, zoning certificates and all other law- Title nd ov related tters:
- Estim of rectification of specific defects.

ific exclusions detailed in AS 4349.1 – 2007 What is not repor

- Footings below damp-proof course, electrical installations, operation of smoke detectors, light switches con d co and fittings, TV, sound nun tion and security systems, concealed plumbing, adequacy of roof drainage as installed, gas fittings and fixtures, air ndition automatic garage door mechanisms, swimming pools and associated filtration and similar equipment;
- The operation of fireplaces are solid coverings, electrical appliances including solid fu heaters, including chimneys and flues, alarm systems, intercom systems, soft floor shers, incinerators, ovens, ducted vacuum systems, paint coatings except external protective coatings, health h ergies, soil toxicity, lead content, radon, presence of asbestos or urea formaldehyde), timber and metal fra dequacy, concealed tie downs and bracing, timber pest activity, other s gates, clina
- mechanical or electrical equipment (sucSoil conditions, control joints, sus t provisions, concealed framing-timbers or any areas concealed by le de opn wall linings or sidings, landscaping, rubbish coy furniture and accessories, stored items, insulation, environmental matters e.g. BASIX, water tanks, BCA environmenta energy efficiency, lighting efficiency.

What is reported on

The inspection includes subjective appraisal by an insp ss the condition of residential buildings. It competent to a involves a subjective assessment so different inspectors or even the same r on a different occasion may reach different

The inspection comprises a visual assessment of the property to iden or defe s and to form an opinion regarding the general condition of the property at the time of inspection. The following be inspected where applicable:

- The interior of the building: ceilings; walls; floors; windows; doors & fran s; kitch<u>en;</u> bathroom; WC; ensuite; laundry; stairs & damp problems;
- The exterior of the building: walls (including lintels, claddings, doors & Indian chimneys; stairs; balconies, verandas, patios, decks, suspended concrete floors or steel frames & structures: imP
- The roof exterior: roof (including tiles, shingles & slates, roof sheeting, gable ights, vents, flues; valleys; guttering; downpipes; eaves, fascia's and barges;

 - ded concrete floors;); susp
- The roof space: roof covering; roof framing; sarking; party walls; insulation;
 The sub-floor space: timber floor (including supports, floor, ventilation, drainage, d
 The property within 30m of the house and within the boundaries of the site: car a hed laundry, ablution facilities and garden sheds; retaining walls (where supporting other structures and landsca s > 700mm high); paths & driveways; steps; fencing (general & swimming pool); surface water (drainage effectivene



4. Terms & Conditions

APBI Terms & Conditions

General

- 1. iSPECT Building Inspections (iSPECT) has prepared this report in accordance with the guidelines of **Australian Standard 4349.1 2007 Inspection of buildings Part 1: Pre-purchase inspections Residential Buildings** (the Standard) which covers the minimum requirements for the visual inspection of residential buildings and based on the inspection of the property by the Inspector named in the building inspection report.
- 2. The Report is prepared for the sole and exclusive use of the Client (person, persons or body) named in the Booking Confirmation and cannot be used or acted upon by any other party without the express permission of iSPECT.
- 3. The Terms and Conditions are available on the website: www.iSPECT.com.au and can change without notice.
- 4. The Client, been provided with the opportunity to read these Terms and Conditions following the making of a booking and a payment for an aspection, accepts these Terms and Conditions.
- 5. The Cent acrowledges that these Terms and Conditions take precedence over any oral or written representations made by iSPECT the Instructor, to the extent of any inconsistency.
- 6. A report provided in acceptance with the Standard is not a certificate of compliance of the property within the requirements of any Act, regulation in the local law or by-law, or as a warranty or an insurance policy against problems developing with the building in the fut fe.

The Inspection

- 7. All inspections will be a **Non-invarie v. val** inspection and will be limited to those areas and sections of the property to which Reasonable Access (see below) is 15th available and permitted on the date and time of Inspection.
- 8. The inspection is undertaken, and the Report Separed, by the Inspector on the assumption that the existing use of the Inspected Property will continue. As each, the Inspector will not assess the fitness of the Inspected Property for any other intended purpose. We advise you to verify any proposed change in use of the Inspected Property with the relevant authorities.
- 9. Where the Inspected Property is a suit of the nominated residence and does not include common property. i.e. Only the eitems listed on the title shall be reported.
- 10. The Inspected Property shall be compared with a base was constructed in accordance with the generally accepted practice at the time of construction and which has been mainly ed such that there has been no significant loss of strength and serviceability.

Reasonable Access

- 11. The Standard provides that "safe and reasonable access" shall be acted by the inspector at the time of the inspection, based on the conditions encountered at the time of inspection. An inspector is all ly inspect areas where safe, unobstructed access is provided and where the minimum clearances are available or, when these clearances are not available, areas within the inspector's unobstructed line of sight and close enough to enable reasonable approximation.
- 12. Minimum clearances are defined as at least 600mm vertical and horizontal character for roof space and sub floor area access. The interior and exterior roof must be accessible from a 3.6 metre high ladder for reason the access to be available.
- 13. Reasonable access does not include removing screws and bolts to access covers. Nor class reasonable access include cutting or making access traps or moving furniture or stored goods.

Limitations

- 14. **No assessment or identification** is made of asbestos or asbestos related products, toxic mount. Methan shetamine or other harmful substances. Asbestos dust is a hazardous material and should not be disturbed. It is vital to trash toxic dot sawn, sanded, drilled or water blasted, etc. For more information about the handling and disposing of asbestos contrat your council.
- 15. Our inspection does not assess the operation of appliances, alarms, security and communication systems, small detectors, heating and cooling systems, blinds (internal and external), soft furnishings, telephones, spa and pool equipment building automation, electrically operated doors, plant and equipment. Any item not specifically noted in this Report is excluded from the inspection of the Inspected Property. We suggest that a licensed tradesperson be contacted for a separate report in respect of gas or electrical appliance and fittings.
- 16. No item of furniture or fixtures will be removed, moved or modified during the inspection and items and conditions covered by such furnishings and fixtures are not inspected or considered. Nor do we assess the condition of conspicuous, non-structural items such as carpets, vinyl floor coverings etc.
- 17. The Inspector can only make comment about the general, visible condition of electrical wiring and plumbing. We suggest that a licensed tradesperson be contacted for a separate report.

The Inspection Report

18. The Report must be read carefully and, in its entirety, to gain a complete understanding of the findings of the inspection of the Inspected Property. It will help you understand the limitations faced by an inspector and why it is not possible to guarantee that a property is completely free of defects.



- 19. This Report describes the visual assessment of the Inspected Property including: the relevant features of the Inspected Property within 30m of the building and within the boundaries of the site, the prevailing structural, soil and weather conditions at the date and time of the inspection.
- 20. The Report is a subjective assessment of the Inspected Property and therefore outlines the opinion of the Inspector on the general condition of the Inspected Property at the date and time of the inspection in relation to major defects or safety hazards and a general advice on minor defect items.
- 21. The Report does not cover any part of the building located beneath the ground surface or identify any unauthorised building work or of work not compliant with building regulations.
- 22. An estimate of the costs of rectification of defects is not required in accordance with the Standard.
- 23. Any maintenance and general advice items are intended as a helpful guide. The Report is not an exhaustive list of all maintenance and advice items.
- 24. The Report provides no guarantee and is not a warranty against problems developing with the Inspected Property in the future.
- 25. This Report is not regorous assessment of all building elements and does not cover all maintenance items. This Report also does not cover all maintenance items. The report also does not cover all maintenance items. This Report also does not cover all maintenance items. The report a
- 26. The Building of Pre-pure ase Inspection Report does not identify the presence of timber pests, or any damage caused by timber pests (e.g., for es, buers, etc.). If you wish to include this, you will need to request a Timber Pest inspection report. If there is a concern egard. The there types of pests then a fully qualified Pest Controller should be contacted.

Other matters

- 27. You should address legal and conceyating matters such as title and ownership to your solicitor or legal representative. Compliance issues in relation to the positioning of services, privacy, vehicle access, the siting of the buildings, zoning, permit or town planning issues or other legal matters should be directed to the relevant authority or to a solicitor or legal representative.
- 28. Unless otherwise notified, iSPEC Suilding Inspections will make vendor purchased reports available to prospective buyers. Please advise within 48 hours of receipt of his report if, as wendor, you do not wish this report to be made available to prospective purchasers of the property.



5. Hallways and general living spaces





	cc dition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Floor					
Walls		Ø			
Ceilings		d			
Doors	₫				
Windows	₫ 🗸				
Fireplace					₫
Stairs	₫				
Balustrade	₫				

Hallways and general living spaces


Minor and/or Major Defect

Walls

Comments

Crack above entry door. Crack is due to stress pointand also footing movement. Builder to at end and rectify







Hallways and general living spaces

Minor and/or Major Defect

Ceilings


Comments

Portion adjacent to garage is repaired. Sanding and painting is required





6. Kitchen





	Con ition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Floor	Ø				
Walls					
Ceilings	d				
Doors					₫
Windows					đ
Cabinets / Drawers	₫	· N			
Benchtops	₫				
Sink/Taps	₫				
Appliances (Oven, Range Hood, Dishwasher)	₫				
Ventilation	₫				
					*



7. Laundry



	Con ition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Floor	Ø				
Walls					
Ceilings	d				
Doors					₫
Windows					₫
Trough/Sink	₫				
Taps	₫				
Cabinets	₫				
Sealants	₫				
Exhaust Fans					
Ventilation			₫ (
					*



Laundry

Minor and/or Major Defect


Exhaust Fans

Comments

There is no exhaust fan installed within laundry area. I noted that there is no window and opening is to the kitchen and not external part of the building. It is mandatory to install exhaust fan and the pipes are to be directed externally and not within ceiling space.












Laundry

Incomplete Item

Ventilation

Comments


There is no exhaust fan installed within laundry area. I noted that there is no window and opening is to the kitchen and not external part of the building. It is mandatory to install exhaust fan and the pipes are to be directed externally and not within ceiling space





8. Bedrooms

8.1. Bedroom 1



	rine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Floor					
Walls	ď				
Ceilings	Ø				
Doors	Ø				
Windows	₫				
Robes	₫				
Smoke Detectors	₫				



8.2. Bedroom 2







	c. dition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Floor					
Walls					
Ceilings	ď				
Doors	V				
Windows	V				
Robes	₫				
Smoke Detectors	₫				



8.3. Bedroom 3





	dition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Floor					
Walls	Ø				
Ceilings	ď				
Doors	₫				
Windows					
Robes	₫				
Smoke Detectors	₫		<u></u>		


Bedroom 3

Minor and/or Major Defect

Windows

Comments


Window is a fixed window and not openable. Mechanical ventilation is not llower lieurof natural ventilation in domestic dwellings without an alternative solution prepared by suitably question of persons and approved by the building surveyor issued the building permit and occupancy permit. I recommend the window to be changed and an openable window to be installed.








8.4. Bedroom 4





	c. `dition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Floor	A				
Walls					
Ceilings	ď				
Doors		₫ 🍌			
Windows	₫ 🗸				
Robes	₫				
Smoke Detectors	₫		<u></u>		

Bedroom 4

Minor and/or Major Defect

Doors

Comments

Door not closing properly. Builder to attend and rectify the issue







9. Bathrooms


9.1. Bathroom 1




	ndit' Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Floor					
Walls	V				
Ceilings	V				
Doors	d				
Windows		1 N			₫
Shower Recess	₫				
Shower Screen	₫				
Shower Rose	J				
Bath	₫				
Taps	J				
Cabinets	J				
Sealants	J				
Basins	₫				
Toilet	₫				
Ventilation	₫				ď

10. Ensuite

10.1. Ensuite 1





	ndit' Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Floor					
Walls	ď				
Ceilings	Ø				
Doors	d				
Windows					₫
Shower Recess	₫				
Shower Screen	I				
Shower Rose	I				
Bath					₫
Taps	I			V	
Cabinets	I				
Sealants	I				
Basins	₫				
Toilet	₫				
Ventilation	₫				ď

11. External of	f property > E	xterior			
	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Walls		₫			
Windows	₫				
Doors	₫				
Fascia, Eaves, Bargeboards	₫				
Down Pipes	₫				
Deck, Vera Balcony, tio					₫
teps					₫
Han					₫
Pergola	, ,				₫
Driveways and Paths	V				
Retaining Walls					₫
Garage/Car Port		ightharpoons			
			? €		




External > Exterior

Minor and/or Major Defect

Comments

Areas inspected externally


















External > Exterior

Minor and/or Major Defect

Walls

Comments

There are some cracks and movements joints on external walls. Crack above lintel is stress point due to loading over lintel. The gaps between windows and brick works and brick piers and wall in garage is due to footing settlement. Builder to consult with structural engineer for cause and rectification procedure.





External > Exterior

Minor and/or Major Defect

Garage/Car Port

Comments

Ceiling plaster is separated from ceiling joists and falling. Builder to attend and rectify the issue.







12. External of property > Roof areas **Roof Type:** Timber truss sually Minor and/or Major Unable to Inspect Due **Not Applicable** Incomplete Item Fine Defect to Access (N/A) **Roof Space** Roof ₫ ₫ **Valleys Flashings** ₫ ₫ Gutters **Pointing** ₫ **Skylights** ₫ Vents ₫ Chimney O/X



External > Roof Areas

Minor and/or Major Defect

Roof

Comments

Tiles above garage had not been laid flat and properly. There are some uplifted tiles which allow rain and moisture enter the roof space. Builder to attend and rectify



External > Roof Areas

Minor and/or Major Defect

Pointing

Comments

Pointing needs to be fixed. Currently many cracks re vis

Builder to attend and rectify







13. External of property > Sub floor areas



	Con ition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)
Sub Floor Ventilation	V				
Stumps					
Framing	V				



14. Findings and summary

This Building Inspection summary provides you with a "snapshot" of the items the inspector considers of greatest significance for you, in respect of the building only, when considering this property. Please refer to the Definitions and the complete Report for detailed information regarding visible defects. Note that this Summary is not the complete Report and that in the event of an apparent discrepancy the complete Report overrides the Summary information.

Report Summary

Overall condition of the property is fine apart from defects identified during inspection and stated within the report.



Major Defects Noted

Yes

A defect of sufficient magnitude where rectification has to be carried out without unsue decrease at the action of the relevant part of the building can no longer serve its intended function; or further substantial deterioration of the building.

Ceiling plaster is falling in garage area. The client advised the ceiling fall occurred previously and seed by an ecompleted. Window in bedroom is fixed and there is not any natural way of ventilation

Major Structural Defects Noted

Yes

A major defect in any internal or external primary load bearing component of the building which seriously affects the structural integrity of the building requiring rectification to be carried out without undue delay to avoid: unsafe conditions, posing a threat to life or serious injury; loss of utility, whereby the defect is such that the whole of the relevant part of the building can no longer serve its intended function; or further substantial deterioration of the building. In the case of cracking, a serious structural defect denotes severe cracking as defined by Category 4, Appendix C – Australian Standard AS 2870-2011. Appendix C is attached for your reference.

Gap between brick piers and walls. Gap between windows and brick works. Structural engineer to comment



15. iSPECT Building Inspections

The iSPECT Building Inspections is a national franchise building inspections business. iSPECT engages with trade qualified builders with a minimum of 10 years residential and commercial building experience to complete property inspections. Each home and building inspection completed is then detailed in a report that is completed to Australian Standards AS4349.0, AS4349.1 and/or AS4349.3. iSPECT has franchises nationally who are supported by a national call centre located at 8 Anderson Street, Port Melbo rne. Our office locations follow:



